

0.05M Tris Buffer (pH 7.6)

(Greg A. Perry, Ph.D.)

Equipment:

1 liter flask/beaker
Stir plate

Stir bar
pH meter

Reagents:

6.06 gm Tris Hydrochloride (Tris-HCl)
1.39 gm Tris Base
1000 ml Distilled Water

Method:

- 1) Combine all ingredients and mix well.
- 2) Adjust to pH 7.6.